



1. .3% East, .3% Lat South
2. 1.2% East, 3% Lat South
3. 1.0 % North, .3% Lat East
4. 6.3% Southwest, .3% Lat East
5. 2.8% Southwest, 2.1 % East (Along Center Path)
6. 5.8 % Southwest, .2% North (Mushroom Tunnel)
7. Landing 1.7% All Directions
8. 4.2% Southwest, 0% Lat
9. 1.9% NE, 5.9% Lat W
10. 15.8% West, .3% North (Crusher path top of cobble stairs)
11. 12.5 % South, 1.7% E, (Labyrinth >27' of downward slope)
12. 6.6% West, 2.8% South
13. 8.4% West, 1.4% South
14. 8.7 % West, 1.4% South
15. 14.4% East, .5% North
16. 7.2% East, 1.0% Northwest
17. 7.9 % North, 1.9% East (>27' from connection to landing)
18. 9.3% Northeast, 4.2% East
19. 5.1% East , 3.7% North
20. 10.8% Northwest, 2.6% East (inaccessible for ADA)
21. 11.2% North, 1.7% West (inaccessible for ADA)
22. 10.5% South, .5% East
23. 5.5-6.3% South, 1.7 % E
24. 12% for 15' South, 0% Lat
25. 10% North, 1% West
26. 13.7% East, 0% Lateral
27. 12.8% Northeast, 2.6% North
28. 8.6% Northeast, 1.7 % North

Note: % Grade measured from point of inflection to point of inflection, grades are reported in Longitudinal followed by cross slope.

EXTENTS OF MEASUREMENT/CONCERN

NOT TO SCALE